

序号	报告编号	发布日期	结论	影像资料	
35	GX-B1385/21-Z-22014	2022/5/17	所检项目合格		 <p>2022 05 01</p>
36	GX-B1385/21-Z-22015	2022/5/17	所检项目合格		 <p>2022 05 01</p>

37	GX-B1515-Z-22001	2022/5/17	所检项目合格		
38	GX-B1307 / 20-Z-22006	2022/5/13	综合判定：合格。		

39	GX-B1307 / 20-Z-22007	2022/5/13	综合判定：合格。		 <p>2022 04 19</p>	
40	GX-B1307 / 20-Z-22008	2022/5/13	综合判定：合格。		 <p>2022 04 19</p>	

41	GX-B1307 / 20-Z-22009	2022/5/13	综合判定：合格。	
42	GX-B1310 / 21-Z-22021	2022/5/18	符合标准要求	

43	GX-B1310 / 21-Z-22022	2022/5/18	符合标准要求		
44	GX-B1310 / 21-Z-22023	2022/5/18	符合标准要求		

45	GX-B1310 / 21-Z-22024	2022/5/18	符合标准要求		
46	GX-B1310 / 21-Z-22025	2022/5/18	符合标准要求		



47	GX-B1310 / 21-Z-22026	2022/5/18	符合标准要求			
48	GX-B1310 / 21-Z-22027	2022/5/18	符合标准要求			

49	GX-B1310 / 21-Z-22028	2022/5/18	符合标准要求			
50	GX-B1313 / 21-Z-22001~22002	2022/5/17	所检项目合格			



51	GX-B1313 / 21-Z-22003	2022/5/17	所检项目合格			
52	GX-B1313 / 21-Z-22006	2022/5/17	所检项目合格			

53	GX-B1313 / 21-Z-22007~22008	2022/5/17	所检项目合格			
54	GX-B1313 / 21-Z-22009~22010	2022/5/17	所检项目合格			

55	GX-B1313 / 21-Z-22011	2022/5/17	所检项目合格			
56	GX-B1322 / 21-Z-22001~22004	2022/5/16	本次共检电力电			

57	GX-B1322 / 21-Z-22005	2022/5/16	所检项目合格		
58	GX-B1322 / 21-Z-22006~22007	2022/5/17	所检项目合格		

59	GX-B1324 / 20-Z-22001	2022/5/16	所检项目合格			
60	GX-B1324 / 20-Z-22002	2022/5/16	所检项目合格			

61	GX-B1328 / 20-Z-22017	2022/5/17	所检项目合格	 <p>2022 04 19</p>
62	GX-B1328 / 20-Z-22018	2022/5/17	所检项目合格	 <p>2022 04 19</p>



63	GX-B1328 / 20-Z-22019	2022/5/17	所检项目合格	
64	GX-B1328 / 20-Z-22020	2022/5/17	所检项目合格	
65	GX-B1328 / 20-Z-22021	2022/5/17	所检项目合格	

66	GX-B1328 / 20-Z-22022	2022/5/17	所检项目合格			
67	GX-B1328 / 20-Z-22023	2022/5/17	所检项目合格			

68	GX-B1328 / 20-Z-22024	2022/5/17	所检项目合格			
69	GX-B1328 / 20-Z-22025	2022/5/17	所检项目合格			

70	GX-B1350/21-Z-22001	2022/5/16	所检项目合格		 <p>2022.04.17</p>
71	GX-B1350/21-Z-22002	2022/5/16	所检项目合格		 <p>2022.04.17</p>

72	GX-B1350/21-Z-22003	2022/5/16	所检项目合格			
73	GX-B1350/21-Z-22004	2022/5/16	所检项目合格			

74	GX-B1350/21-Z-22005	2022/5/16	所检项目合格			
75	GX-B1350/21-Z-22006	2022/5/16	所检项目合格			



76	GX-B1350/21-Z-22007	2022/5/16	所检项目合格		 <p>2022.04.17</p>	
77	GX-B1350/21-Z-22008	2022/5/16	所检项目合格		 <p>2022.04.17</p>	

78	GX-B1350/21-Z-22009	2022/5/16	所检项目合格		 <p>2022.04.17</p>	
79	GX-B1350/21-Z-22010	2022/5/16	所检项目合格		 <p>2022.04.17</p>	

80	GX-B1350/21-Z-22011	2022/5/16	所检项目合格		 A person wearing a dark jacket and a headlamp is inspecting a component in a dark environment. The headlamp is on, illuminating the work area. A date stamp '2022.04.17' is visible in the bottom right corner of the image.	
81	GX-B1350/21-Z-22012	2022/5/16	所检项目合格		 A person wearing an orange protective suit, a helmet with a headlamp, and a face shield is inspecting a blue and red structure. The person is holding a tool or device. A date stamp '2022.04.17' is visible in the bottom right corner of the image.	



82	GX-B1350/21-Z-22013	2022/5/16	所检项目合格			
83	GX-B1350/21-Z-22014	2022/5/16	所检项目合格			

84	GX-B1350/21-Z-22015	2022/5/16	所检项目合格			
85	GX-B1350/21-Z-22016	2022/5/16	所检项目合格			

86	GX-B1350/21-Z-22017	2022/5/16	所检项目合格		 <p>2022.04.17</p>	
87	GX-B1350/21-Z-22018	2022/5/16	所检项目合格		 <p>2022.04.17</p>	



88	GX-B1350/21-Z-22019	2022/5/16	所检项目合格			
89	GX-B1350/21-Z-22020	2022/5/16	所检项目合格			

90	GX-B1350/21-Z-22021	2022/5/16	所检项目合格		 <p>2022.04.17</p>	
91	GX-B1350/21-Z-22022	2022/5/16	所检项目合格		 <p>2022.04.17</p>	

92	GX-B1350/21-Z-22023	2022/5/16	所检项目合格		 A person wearing a dark helmet with a headlamp and a dark jacket with a reflective strip is shown in a dark environment. They are holding a small electronic device, possibly a detector or scanner, and looking at it. The scene is illuminated by the headlamp and some ambient light. A timestamp "2022.04.17" is visible in the bottom right corner of the image.	
93	GX-B1350/21-Z-22024	2022/5/16	所检项目合格		 A person wearing a red jacket and a dark helmet with a headlamp is shown in a dark environment. They are working on a piece of equipment, possibly a detector or scanner, and looking at it. The scene is illuminated by the headlamp and some ambient light. A timestamp "2022.04.18" is visible in the bottom right corner of the image.	

94	GX-B1350/21-Z-22025	2022/5/16	所检项目合格			
95	GX-B1350/21-Z-22026	2022/5/16	所检项目合格			

96	GX-B1350/21-Z-22027	2022/5/16	所检项目合格	 <p>2022.04.18</p>
97	GX-B1350/21-Z-22028	2022/5/16	所检项目合格	 <p>2022</p>

98	GX-B1350/21-Z-22029	2022/5/16	所检项目合格		 <p>2022.04.18</p>	
99	GX-B1350/21-Z-22030	2022/5/16	所检项目合格		 <p>2022.04.18</p>	

100	GX-B1350/21-Z-22031	2022/5/16	所检项目合格		 <p>2022.04.18</p>	
101	GX-B1350/21-Z-22032	2022/5/16	所检项目合格		 <p>2022.04.18</p>	



102	GX-B1350/21-Z-22033	2022/5/16	所检项目合格			
103	GX-B1350/21-Z-22034	2022/5/16	所检项目合格			

104	GX-B1350/21-Z-22035	2022/5/16	所检项目合格			
105	GX-B1350/21-Z-22036	2022/5/16	所检项目合格			

106	GX-B1350/21-Z-22037	2022/5/16	所检项目合格		 <p>2022.04.19</p>	
107	GX-B1350/21-Z-22038	2022/5/16	所检项目合格		 <p>2022.04.19</p>	

108	GX-B1350/21-Z-22039	2022/5/16	所检项目合格		 <p>2022.04.19</p>
109	GX-B1350/21-Z-22040	2022/5/16	所检项目合格		 <p>2022.04.19</p>

110	GX-B1350/21-Z-22041	2022/5/16	所检项目合格	 <p>A worker wearing an orange safety suit, a black helmet with a headlamp, and a blue face mask is working on a piece of equipment. The worker is holding a smartphone in their right hand. The background shows a white wall with some equipment and a red and blue striped barrier. A timestamp '2022.04.19' is visible in the bottom right corner of the photo.</p>
111	GX-B1350/21-Z-22042	2022/5/16	所检项目合格	 <p>A worker wearing a dark safety suit with a bright reflective stripe, a black helmet with a headlamp, and a blue face mask is working on a piece of equipment. The worker is holding a smartphone in their right hand. The background is dark, and the worker's headlamp is on. A timestamp '2022.04.19' is visible in the bottom right corner of the photo.</p>


112	GX-B1350/21-Z-22043	2022/5/16	所检项目合格			
113	GX-B1350/21-Z-22044	2022/5/16	所检项目合格			

114	GX-B1350/21-Z-22045	2022/5/16	所检项目合格			
115	GX-B1350/21-Z-22046	2022/5/16	所检项目合格			





116	GX-B1350/21-Z-22047	2022/5/16	所检项目合格			
117	GX-B1350/21-Z-22048	2022/5/16	所检项目合格			

118	GX-B1350/21-Z-22049	2022/5/16	所检项目合格			
119	GX-B1350/21-Z-22050	2022/5/16	所检项目合格			

120	GX-B1350/21-Z-22051	2022/5/16	所检项目合格		 <p>2022.04.17</p>	
121	GX-B1350/21-Z-22052	2022/5/16	所检项目合格			

122	GX-B1350/21-Z-22053	2022/5/16	所检项目合格	 <p>2022.04.19</p>
123	GX-B1350/21-Z-22054	2022/5/16	所检项目合格	 <p>2022.04.19</p>

124	GX-B1350/21-Z-22055	2022/5/16	所检项目合格		 <p>2022.04.19</p>	
125	GX-B1350/21-Z-22056	2022/5/16	所检项目合格		 <p>2022.04.19</p>	

126	GX-B1350/21-Z-22057	2022/5/16	所检项目合格	 <p>A worker in an orange safety suit and helmet is working on a structure at night. The worker is wearing a black helmet with a headlamp and is holding a tool. The background is dark with some lights. A date stamp '2022.04.19' is visible in the bottom right corner of the image.</p>
127	GX-B1350/21-Z-22058	2022/5/16	所检项目合格	 <p>A worker in an orange safety suit and helmet is working on a structure at night. The worker is wearing a black helmet with a headlamp and is holding a tool. The background is dark with some lights. A date stamp '2022.04.19' is visible in the bottom right corner of the image.</p>

128	GX-B1350/21-Z-22059	2022/5/16	所检项目合格			
129	GX-B1350/21-Z-22060	2022/5/16	所检项目合格			



130	GX-B1350/21-Z-22061	2022/5/16	所检项目合格			
131	GX-B1350/21-Z-22062	2022/5/16	所检项目合格			



132	GX-B1350 / 21-Z-22057	2022/5/16	所检项目合格	
133	GX-B1350 / 21-Z-22063	2022/5/16	所检项目合格	

134	GX-B1350 / 21-Z-22064	2022/5/17	所检项目合格			
135	GX-B1350 / 21-Z-22065	2022/5/17	所检项目合格			


136	GX-B1350 / 21-Z-22066	2022/5/17	所检项目合格			
137	GX-B1350 / 21-Z-22067	2022/5/17	所检项目合格			

138	GX-B1351/21-Z-22001~ 22002	2022/5/16	所检项目合格		 A photograph showing a person wearing a red hard hat and using a flashlight to inspect the interior of an electrical cabinet. The cabinet is open, revealing various electrical components and wiring. The scene is dimly lit, with the primary light source being the flashlight. A timestamp '2022 04 19' is visible in the bottom right corner of the image.	
139	GX-B1351/21-Z-22003~ 22004	2022/5/16	所检项目合格		 A photograph showing a person wearing a red hard hat and using a flashlight to inspect the interior of an electrical cabinet. The cabinet is open, revealing various electrical components and wiring. The scene is dimly lit, with the primary light source being the flashlight. A timestamp '2022 04 19' is visible in the bottom right corner of the image.	

140	GX-B1352/21-Z-22001	2022/5/16	所检项目合格			
141	GX-B1352/21-Z-22002~ 22003	2022/5/16	所检项目合格			

142	GX-B1352/21-Z-22004	2022/5/16	所检项目合格		 <p>2022 04 17</p>	
143	GX-B1352/21-Z-22005	2022/5/16	所检项目合格		 <p>2022 04 17</p>	



144	GX-B1352/21-Z-22006	2022/5/16	所检项目合格			
145	GX-B1352/21-Z-22007	2022/5/16	所检项目合格			

146	GX-B1352/21-Z-22008	2022/5/16	所检项目合格			
147	GX-B1352/21-Z-22009	2022/5/16	所检项目合格			

148	GX-B1352/21-Z-22010~22011	2022/5/16	所检项目合格		
149	GX-B1352/21-Z-22012	2022/5/16	所检项目合格		

150	GX-B1352/21-Z-22013	2022/5/16	所检项目合格		 <p>2022 04 17</p>	
151	GX-B1352/21-Z-22014	2022/5/17	所检项目合格		 <p>2022 04 17</p>	



152	GX-B1352/21-Z-22015	2022/5/16	所检项目合格			
153	GX-B1352/21-Z-22016	2022/5/16	所检项目合格			

154	GX-B1352/21-Z-22017	2022/5/16	所检项目合格			
155	GX-B1352/21-Z-22018	2022/5/16	所检项目合格			

156	GX-B1352/21-Z-22019~ 22020	2022/5/16	所检项目合格			
157	GX-B1352/21-Z-22021~ 22022	2022/5/16	所检项目合格			



158	GX-B1352/21-Z-22023~ 22024	2022/5/16	所检项目合格			
159	GX-B1352/21-Z-22025~ 22027	2022/5/16	所检项目合格			

160	GX-B1352/21-Z-22028~ 22029	2022/5/16	所检项目合格			
161	GX-B1352/21-Z-22030	2022/5/16	所检项目合格			

162	GX-B1352/21-Z-22031~ 22042	2022/5/16	所检项目合格			
163	GX-B1352/21-Z-22043	2022/5/16	所检项目合格			

164	GX-B1352/21-Z-22044	2022/5/16	所检项目合格		 <p>2022 04 18</p>	
165	GX-B1352/21-Z-22045~ 22046	2022/5/16	所检项目合格		 <p>2022 04 18</p>	

166	GX-B1352/21-Z-22047~ 22049	2022/5/16	所检项目合格			
167	GX-B1352/21-Z-22050~ 22051	2022/5/16	所检项目合格			

168	GX-B1352/21-Z-22052~ 22053	2022/5/16	所检项目合格		 <p>2022 04 18</p>	
169	GX-B1352/21-Z-22054~ 22063	2022/5/16	所检项目合格		 <p>2022 04 18</p>	

170	GX-B1352/21-Z-22064	2022/5/16	所检项目合格			
171	GX-B1352/21-Z-22065~ 22066	2022/5/16	所检项目合格			



172	GX-B1352/21-Z-22067	2022/5/16	所检项目合格			
173	GX-B1352/21-Z-22068	2022/5/16	所检项目合格			

174	GX-B1352/21-Z-22069~ 22070	2022/5/16	所检项目合格			
175	GX-B1352/21-Z-22071~ 22072	2022/5/16	所检项目合格			

176	GX-B1352/21-Z-22073	2022/5/16	所检项目合格		 <p>2022 04 19</p>	
177	GX-B1352/21-Z-22074	2022/5/16	所检项目合格		 <p>2022 04 19</p>	

178	GX-B1352/21-Z-22075~ 22077	2022/5/16	所检项目合格		 <p>2022 04 19</p>	
179	GX-B1352/21-Z-22078~ 22079	2022/5/16	所检项目合格		 <p>2022 04 18</p>	



180	GX-B1352/21-Z-22080~ 22081	2022/5/16	所检项目合格			
181	GX-B1352/21-Z-22082~ 22083	2022/5/16	所检项目合格			



182	GX-B1352/21-Z-22084	2022/5/16	所检项目合格			
183	GX-B1352/21-Z-22085~ 22087	2022/5/16	所检项目合格			



184	GX-B1352/21-Z-22088~ 22089	2022/5/16	所检项目合格			
185	GX-B1352/21-Z-22090~ 22091	2022/5/16	所检项目合格			



186	GX-B1352/21-Z-22092~ 22093	2022/5/16	所检项目合格		 <p>2022 04 19</p>	
187	GX-B1352/21-Z-22094	2022/5/16	所检项目合格		 <p>2022 04 19</p>	

188	GX-B1354/20-Z-22003	2022/5/16	电网接地电容电	
189	GX-B1354/20-Z-22004	2022/5/16	电网接地电容电	

190	GX-B1359/21-Z-22001~ 22002	2022/5/16	所检项目合格		 <p>2022 04 17</p>	
191	GX-B1359/21-Z-22003	2022/5/16	所检项目合格		 <p>2022 04 17</p>	

192	GX-B1359/21-Z-22004~ 22006	2022/5/16	所检项目合格	 <p>A photograph showing several workers in a confined space, likely a tunnel or underground facility. They are wearing blue work clothes and red hard hats. One worker in the foreground is kneeling and working on a piece of equipment, illuminated by a bright light. Other workers are visible in the background, also wearing hard hats and using lights. The scene is dimly lit, with the primary light sources being the workers' headlamps and work lights. A timestamp '2022 04 17' is visible in the bottom right corner of the image.</p>
193	GX-B1359/21-Z-22007~ 22009	2022/5/16	所检项目合格	 <p>A photograph showing workers in a confined space, similar to the one above. The workers are wearing blue work clothes and red hard hats. They are illuminated by bright work lights, creating a high-contrast scene. The workers appear to be focused on their task, with one worker in the foreground being particularly prominent. The background shows the interior of a tunnel or underground facility with various pieces of equipment and structural elements.</p>

194	GX-B1359/21-Z-22010	2022/5/16	所检项目合格		 <p>2022 04 17</p>	
195	GX-B1359/21-Z-22011~22012	2022/5/16	所检项目合格		 <p>2022 04 17</p>	

196	GX-B1359/21-Z-22013~ 22014	2022/5/16	所检项目合格		 <p>2022 04 17</p>	
197	GX-B1359/21-Z-22015	2022/5/16	所检项目合格		 <p>2022 04 17</p>	

198	GX-B1359/21-Z-22016	2022/5/16	所检项目合格			
199	GX-B1359/21-Z-22017~22018	2022/5/16	所检项目合格			



200	GX-B1359/21-Z-22019	2022/5/16	所检项目合格			
201	GX-B1359/21-Z-22020~22021	2022/5/16	所检项目合格			

202	GX-B1359/21-Z-22022~ 22023	2022/5/16	所检项目合格			
203	GX-B1359/21-Z-22024	2022/5/16	所检项目合格			

204	GX-B1359/21-Z-22025	2022/5/16	所检项目合格			
205	GX-B1359/21-Z-22026	2022/5/16	所检项目合格			

206	GX-B1359/21-Z-22027~ 22028	2022/5/16	所检项目合格	
207	GX-B1359/21-Z-22029~ 22030	2022/5/16	所检项目合格	

208	GX-B1359/21-Z-22031~ 22032	2022/5/16	所检项目合格			
209	GX-B1359/21-Z-22033~ 22034	2022/5/16	所检项目合格			

210	GX-B1359/21-Z-22035	2022/5/16	所检项目合格			
211	GX-B1359/21-Z-22036~22037	2022/5/16	所检项目合格			


212	GX-B1359/21-Z-22038	2022/5/16	所检项目合格			
213	GX-B1359/21-Z-22039	2022/5/16	所检项目合格			

214	GX-B1359/21-Z-22040	2022/5/16	所检项目合格			
215	GX-B1359/21-Z-22041~22042	2022/5/16	所检项目合格			



216	GX-B1359/21-Z-22043	2022/5/16	所检项目合格		 <p>2022 04 17</p>	
217	GX-B1359/21-Z-22044	2022/5/16	所检项目合格		 <p>2022 04 17</p>	



218	GX-B1359/21-Z-22045	2022/5/16	所检项目合格			
219	GX-B1359/21-Z-22046~ 22047	2022/5/16	所检项目合格			


220	GX-B1359/21-Z-22048	2022/5/16	所检项目合格			
221	GX-B1359/21-Z-22049~ 22050	2022/5/16	所检项目合格			

222	GX-B1359/21-Z-22051	2022/5/16	所检项目合格			
223	GX-B1359/21-Z-22052	2022/5/16	所检项目合格			



224	GX-B1359/21-Z-22053	2022/5/16	所检项目合格		 <p>2022 04 19</p>	
225	GX-B1359/21-Z-22054	2022/5/16	所检项目合格		 <p>2022 04 19</p>	



226	GX-B1359/21-Z-22055~ 22057	2022/5/16	所检项目合格			
227	GX-B1359/21-Z-22058~ 22059	2022/5/16	所检项目合格			

228	GX-B1359/21-Z-22060	2022/5/16	所检项目合格		 <p>2022 04 19</p>	
229	GX-B1359/21-Z-22061	2022/5/16	所检项目合格		 <p>2022 04 19</p>	

230	GX-B1424 / 20-Z-22003	2022/5/12	依据NB/T 10176-2019单轨 吊车所检项目合 格；依据MT/T 220-1990 尾气 所检项目合格。		 <p>2022 04 26</p>
231	GX-B1424 / 20-Z-22004	2022/5/12	依据NB/T 10176-2019单轨 吊车所检项目合 格；依据MT/T 220-1990 尾气 所检项目合格。		 <p>2022 04 26</p>





232	GX-B1424 / 20-Z-22005	2022/5/12	依据NB/T 10176-2019单轨 吊车所检项目合 格；依据MT/T 220-1990 尾气 所检项目合格。		 <p>2022 04 26</p>
233	GX-B1424 / 20-Z-22006	2022/5/17	依据NB/T 10176-2019单轨 吊车所检项目合 格；依据MT/T 220-1990 尾气 所检项目合格。		 <p>2022 04 29</p>

234	GX-B1451 / 20-Z-22001~22002	2022/5/16	所检项目合格			
235	GX-B1451 / 20-Z-22003~22008	2022/5/16	所检项目合格			



236	GX-B1451 / 20-Z-22009~22018	2022/5/17	所检项目合格		 <p>2022 04 27</p>
237	GX-B1451 / 20-Z-22019~22022	2022/5/17	所检项目合格		 <p>2022 04 27</p>

238	GX-B1451 / 20-Z-22023	2022/5/17	所检项目合格	
239	GX-B1451 / 20-Z-22024	2022/5/16	所检项目合格	

240	GX-B1520 / 20-Z-22010	2022/5/13	综合判定：合格。		 <p>2022 05 03</p>
241	GX-B1313 / 20-Z-22004~22005	2022/5/17	所检项目合格		 <p>2022 04 19</p>

242	GX-B1308 / 21-Z-22002	2022/5/18	所检项目合格			
243	GX-B1308 / 21-Z-22003	2022/5/18	所检项目合格			



244	GX-B1308 / 21-Z-22004	2022/5/18	所检项目合格	
245	GX-B1308 / 21-Z-22005	2022/5/18	所检项目合格	
246	GX-B1499/21-Z-22017 ~ 22020	2022/5/18	所检项目合格	

247	GX-B1499/21-Z-22021~22025	2022/5/18	所检项目合格	
248	GX-B1499/21-Z-22026~22028	2022/5/18	所检项目合格	
249	GX-B1499/21-Z-22029~22031	2022/5/18	所检项目合格	
250	GX-B1499/21-Z-22021	2022/5/18	所检项目合格	
251	GX-B1500/21-Z-22001	2022/5/17	所检项目合格	



252	GX-B1500/21-Z-22002	2022/5/17	所检项目合格			
253	GX-B1500/21-Z-22003	2022/5/17	所检项目合格			

254	GX-B1500/21-Z-22004	2022/5/17	所检项目合格			
255	GX-B1500/21-Z-22005	2022/5/17	所检项目合格			

256	GX-B1500/21-Z-22006	2022/5/17	所检项目合格	
257	GX-B1500/21-Z-22007	2022/5/17	所检项目合格	

258	GX-B1309/21-Z-22001	2022/5/17	所检项目合格			
259	GX-B1309/21-Z-22002	2022/5/17	所检项目合格			