


序号	报告编号	发布日期	结论	影像资料
101	GX-B1367/22-A-23078	2023/8/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
102	GX-B1367/22-A-23082	2023/8/11	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
103	GX-B1364/22-A-23726	2023/8/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
104	GX-B1364/22-A-23677	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
105	GX-B1364/22-A-23678	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
106	GX-B1364/22-A-23679	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
107	GX-B1364/22-A-23689	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
108	GX-B1364/22-A-23688	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
109	GX-B1364/22-A-23687	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
110	GX-B1364/22-A-23685	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
111	GX-B1364/22-A-23684	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
112	GX-B1364/22-A-23683	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
113	GX-B1364/22-A-23682	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
114	GX-B1364/22-A-23686	2023/8/10	所检项目合格。	 <p>2023/07/29</p>

序号	报告编号	发布日期	结论	影像资料
115	GX-B1364/22-A-23719	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
116	GX-B1364/22-A-23718	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
117	GX-B1364/22-A-23728	2023/8/10	所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
118	GX-B1364/22-A-23723	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
119	GX-B1364/22-A-23721	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
120	GX-B1364/22-A-23722	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
121	GX-B1364/22-A-23724	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
122	GX-B1364/22-A-23725	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
123	GX-B1364/22-A-23727	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
124	GX-B1364/22-A-23729	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
125	GX-B1364/22-A-23666	2023/8/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
126	GX-B1364/22-A-23667	2023/8/9	所检项目合格。	 <p>The photograph shows an indoor industrial or laboratory setting. Two men in light-colored short-sleeved shirts are present. One man is standing on the left, looking towards the right. The other man is standing on the right, facing a white cabinet or piece of equipment. The room has a concrete wall on the left and a window in the background. A date stamp '2023/07/25' is visible in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
127	GX-B1364/22-A-23668	2023/8/9	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
128	GX-B1364/22-A-23701	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
129	GX-B1364/22-A-23695	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
130	GX-B1364/22-A-23704	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
131	GX-B1364/22-A-23709	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
132	GX-B1364/22-A-23708	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
133	GX-B1364/22-A-23707	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
134	GX-B1364/22-A-23706	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
135	GX-B1364/22-A-23705	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
136	GX-B1364/22-A-23703	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
137	GX-B1364/22-A-23702	2023/8/10	所检项目合格。	 <p>The photograph captures two individuals, likely technicians, in a professional setting. They are wearing grey work shirts with a logo on the back. They are positioned in front of a large, dark-colored industrial control cabinet. The cabinet features a prominent digital display screen and several analog gauges or meters. The background shows a room with white walls, a window, and some overhead pipes. A date stamp '2023/07/28' is overlaid on the bottom right of the image.</p>

序号	报告编号	发布日期	结论	影像资料
138	GX-B1364/22-A-23699	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
139	GX-B1364/22-A-23697	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
140	GX-B1364/22-A-23696	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
141	GX-B1364/22-A-23694	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
142	GX-B1364/22-A-23693	2023/8/10	所检项目合格。	 <p>The photograph shows two individuals in light blue work uniforms standing in front of a large, dark-colored industrial machine. The machine has a control panel at the bottom with several red digital displays and buttons. A tall, white chimney stack is visible behind the machine, extending towards a window. The window shows some greenery outside. The date '2023/07/28' is printed in white in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
143	GX-B1364/22-A-23692	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
144	GX-B1364/22-A-23700	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
145	GX-B1364/22-A-23698	2023/8/10	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
146	GX-B1363/22-A-23120	2023/8/15	所检项目合格。	 <p>The photograph shows two men in light blue work shirts inspecting a large, rusted industrial machine. The machine has a prominent vertical pipe on top and several doors with handles. One door is open, and the men are looking inside. A date stamp '2023/08/02' is visible in the bottom right corner of the image. There are also yellow warning labels on the machine.</p>

序号	报告编号	发布日期	结论	影像资料
147	GX-B1363/22-A-23339	2023/8/15	所检项目合格。	 <p>The image shows two technicians in light blue uniforms inspecting a large, rusted metal electrical cabinet. One technician is wearing gloves and looking into the cabinet. The other is standing to the left. The cabinet has a yellow warning sign with a lightning bolt symbol. A date stamp '2023/08/04' is visible in the bottom right corner of the photo. The background shows a window and a green trash bin.</p>

序号	报告编号	发布日期	结论	影像资料
148	GX-B1363/22-A-23330	2023/8/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
149	GX-B1363/22-A-23340	2023/8/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
150	GX-B1363/22-A-23341	2023/8/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
151	GX-B1363/22-A-23346	2023/8/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
152	GX-B1364/22-A-23737	2023/8/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
153	GX-B1364/22-A-23741	2023/8/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
154	GX-B1364/22-A-23742	2023/8/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
155	GX-B1364/22-A-23746	2023/8/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
156	GX-B1366/20-A-23087	2023/8/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
157	GX-B1366/20-A-23088	2023/8/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
158	GX-B1366/20-A-23086	2023/8/15	所检项目全部合格。	 <p>The photograph captures three individuals in white lab coats, each with the '中检公信' logo on the back, engaged in a technical task. They are positioned around a large, complex industrial machine, likely a tensile testing machine, which features a prominent circular dial and a control interface. The setting is a laboratory with white walls and yellow curtains in the background. A date stamp '2023/07/27' is overlaid in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
159	GX-B1365/20-A-23055	2023/8/15	所检项目全部合格。	 <p>The photograph captures three individuals in white lab coats, each with the '中检公信' (Zhongjian Gongxin) logo on the back, engaged in a technical inspection. They are positioned around a large, green industrial testing machine, likely a universal testing machine. One person is looking at a large circular dial on the machine, while another is looking at a document. A third person is standing to the right, observing. The machine has a safety cage and a warning sign. A date stamp '2023/07/31' is visible in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
160	GX-B1365/20-A-23053	2023/8/15	所检项目全部合格。	 <p>The photograph captures three individuals in white lab coats, each with the '中检公信' (Zhongjian Gongxin) logo on the back, engaged in a technical task. They are positioned around a large, complex industrial machine, likely a universal testing machine, which features a prominent circular dial and various mechanical components. The setting is a laboratory or industrial workshop, with yellow curtains visible in the background. A date stamp '2023/07/22' is located in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
161	GX-B1366/20-A-23091	2023/8/22	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
162	GX-B1365/20-A-23054	2023/8/22	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
163	GX-B1365/20-A-23057	2023/8/22	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
164	GX-B1366/20-A-23090	2023/8/22	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
165	GX-B1366/20-A-23089	2023/8/22	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
166	GX-B1364/22-A-23732	2023/8/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
167	GX-B1364/22-A-23738	2023/8/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
168	GX-B1364/22-A-23739	2023/8/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
169	GX-B1364/22-A-23740	2023/8/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
170	GX-B1364/22-A-23736	2023/8/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
171	GX-B1364/22-A-23731	2023/8/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
172	GX-B1364/22-A-23735	2023/8/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
173	GX-B1364/22-A-23745	2023/8/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
174	GX-B1364/22-A-23744	2023/8/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
175	GX-B1364/22-A-23743	2023/8/22	所检项目合格。	